


Notification of Change: L-LAS-TB-Scope V5.4.1 to V5.4.2

This document summarises the changes that were made with the software update from **L-LAS-TB-Scope V5.4.1 to V5.4.2**.

Bug-Fix in V5.4.2:

	After requesting data with the GET button, the tracked video threshold is correctly transmitted in version V5.4.2.
